STATION SCHEDULE

LEGEND

Air Valve	Av
Bellisha Beacon	BB
Borehole	BH
Rubbish Bin	Bin
Bollard	Bol
Bus Stop	Bs
Telecom Point	BT
Camera	Cam
Control Box	Cbox
Closed Circuit TV	Cctv
Chamber Covers	Cv
Down Pipe	Dp
Eaves Height	Eave
Electric Box	Ebox
Electric Post	Ep
Earth Rod	Er
Fire Hydrant	Fh
Flood light	Fl
Flat Roof	Flat
Flag Staff	Fs
Gas Marker	Gmkr
Gate Post	Gp
Gas Valve	Gv
Gully	Gy
Illuminated Bollard	IB
Inspection Cover	IC
Inspection Cover Undefined	Icu
Floor Level	IFL
Invert Level	Inv
Kerb Outlet	Ko
Letter Box	LBox
Lamp post	Lp
Manholes	MH
Marker Post	Mkr
Piezometer	Piez
Pipe Invert	Pinv
Trial Pit	Pit
Parking Meter	PM
Posts	Post
Ridge Height	Ridge
Road Name Board	Rnb
Rodding Eye	Re
Speed Camera	SC
Soffit Level	So
Sign Post	Sp
Stile	St
Tree Stump	Stmp
Stop Tap	St
Stop Valve	Sv
Cable Stay	Sy
Tree Height	THgt
Threshold Level	THL
Traffic Light	TL
Telegraph Post	Tp
Traffic Signal	TS
Top of Wall	TW
Unable to Lift	UTL
Valve	Va
Vent Pipe	Vp
Water Level	WL
Water Meter	Wm
Wash Out	Wo

STA1	Survey Station
	Channel Line
	Centre Line
	Edge of Vegetation
	Fence Open
	Fence Panel
	Fence Secure
	Gate
	Hedge
	O/H Utilities
	Top of Face

REVISIONS

OAKES SURVEYS LTD
8 The Heritage Business Centre, Derby Road,
Belper, Derbyshire, DE56 1SW
Tel : 01773 820124 Fax : 01773 825407
E : info@oakessurveys.com W : www.oakessurveys.com

Client
LAMBLEY
PARISH COUNCIL

Location
LAMBLEY
CEMETERY

Title
GRAVE POSITION
SURVEY

Level Datum
Ordnance Survey

Grid Datum
Ordnance Survey

Project Number	Drawing Reference
3641	3641_A

Surveyor	Checked	Date	Scale
AJB	JF	08.10.12	1:200@A1

Comments.

The plan and digital data should only be used for its original intended purpose at the defined survey scale.
It is for the use only of the party to whom it has been addressed and no responsibility is accepted to any third party for the whole or part of its contents. This survey has been prepared on the basis that all information and facts, which may affect the survey, have been disclosed to us by the parties concerned and no liability or responsibility can be accepted, unless full disclosure has been made.

All ground features that were visible at the time of the survey have been located, however there may have been items obscured.

Pipe sizes and flow direction have been visually assessed from the surface and should be considered as approximate only.

All data remains the ownership of Oakes Survey Services until full payment has been received.

ISO 9001
01004/7/9860 FM04